


HERA-B: Winter shutdown 1999/2000 Schedule



Summary		Task Progress		Critical Task Progress		Milestone		Milestone done	
Task		Critical Task		Baseline		Baseline Milestone			

HERA-B: Winter shutdown 1999/2000 Schedule

- 61 Cleanup pipes and cables in magnet, rearrange false floors -x**
-x side of magnet closed during this time.
- 62 Cleanup pipes and cables in magnet, rearrange false floors +x**
+x side of magnet closed during this time.
- 93 Install and align MS13+**
Open PC2 and PC3 by 2m for alignment of MS13+ and -.
- 96 Install and align MS10+**
Open MC8 for alignment of MS10 + and -.